

FIG.1




FIG.2




FIG. 3




FIG. 4




FIG.5

OPTICAL DISK 85




FIG.6




FIG.7




FIG. 8




FIG.9





FIG. 9

FIG. 10



106110" 22159460

FIG. 11




FIG.12A




FIG.12B




FIG.12C




FIG.12D




FIG.12E




FIG.13A




FIG.13B




FIG.13C




FIG. 14




FIG.15A




FIG.15B




FIG.16A




FIG.16B

